

## SCAN MARINE/WALLAS

### 95D Fan motor replacement



Applies to models 95DU, 95DP, 125DU and 125DP

Warning! If you own one of these products, please run the following test as soon as possible:

Lift the lid (if the unit has a lid) and start the unit. With the cabin area quiet, listen to the unit running. Only the clicking of the fuel pump and the whirr of the combustion fan should be heard.

Listen carefully to the combustion fan – it should be virtually silent. **If it makes any significant noise, it should be replaced ASAP.** This small motor has a 500 to 1,000 hour service life.

If noisy at all, the fan has slowed and air to the combustion chamber is reduced, causing premature internal sooting, along with increasingly reduced performance. If this motor goes to a dead short condition, it can cause the main PCB to fail – resulting in a very expensive repair.

Though the price of the motor itself is only about \$45.00 the complexity of the replacement process will very likely necessitate sending the unit to Scan Marine, where we can install the motor during normal servicing.

Please feel free to contact us by e-mail or phone for additional details on this or other topics.

Questions? Call 1-888-606-6665 toll free!

Thank you.